

## N43RF ERROR SUMMARY TS Earl





Flight ID: 20160803I1

Sensor or system Number or Name

Static Pressure ProbePSM.2Dynamic Pressure ProbePQM.2Total Temperature ProbeTTM.1Dewpoint Temp. ProbeTDM.2

Vertical Accelerometer AccZfilterI-GPS.1

Altimeter AltGPS.3

INE Selection 1

Differential Attack Pressure Probe

Differential Sideslip Pressure Probe

PDBETA.1

Dynamic Attack Pressure Probe

PQALPHA.1

Dynamic Sideslip Pressure Probe

PQBETA.1

Flight Directory acdata/2016/MET/20160803I1

Local Met Data: <u>Takeoff - (0628Z) KMCF</u> <u>Landing - (1350Z) KMCF</u>

Aircraft Static Pressure 1016.7 mb 1016.6 mb Tower Pressure (corrected) 1016.9 mb 1017.3 mb

Notes:

There were no edits made in the measured parameters used to calculate meteorological and navigational parameters.

Takeoff/Landing data: Data during landing and takeoff are potentially suspect. It is recommended that ground data not be used for scientific analysis.

- EMC Tasking.
- TDM.1 failed during a large portion of the flight within the ops area. TDM.2 performed well and was used as the source dewpoint sensor for this mission.

Expendable Type	Number deployed	Number good	Number of messages transmitted
GPS dropwindsonde	11	10	10
AXBT	0	0	0
Test Sondes	0	0	0